

ACE/88/BBR37/15-16

M. A. R. 57 (Rule 116)

Ar 28-5-15

Measurement Book

No. B

341710

Reference to last measurement 8

Serial No. 1st & final.

Time of Work Improvements to Vinayaka Layout & Medarahalli Govt. School back side area in ward no 12 SSD From To

Time of Contractor of nature of Agency Technical Manager (West) KRIDL SC 1-012-14-000042

Date of commencement of work NO FE 10/10/1981 13-14 DL 27/6/14.

Est cost 47.0

Date	Full description, etc, of work 2	Dimensions				Contents 7	Reference to last Measurement 8
		Number 3	Length 4	Breadth 5	Depth 6		
5-1	Earth work in surface excavation in ordinary soil for levelling & lowering the ground manually (other than foundation of buildings, culverts, road drains, pipe lines & cables) and removing the excavated stuff to a distance not exceeding 50m & lift upto 1.5m excavated surface levelled & neatly dressed disposed earth to be levelled after breaking of clods complete as per specifications Qty vide pg no 341702/1 of this M.B.					609.04 cum @ 177 = 12 13 - 107873.00	

M. A. R. 57 (Rule 116)
Measurement Book

No. B

341714

ence No.
st
ement
ame of Work From To
ame of Contractor of nature of Agency
te of commencement of work

Full description, etc., of work 2	Dimensions				Contents 7	Reference to last Measurement 8
	Number 3	Length 4	Breadth 5	Depth 6		
1st main road (0 to 148.0M) csbl 28/5 EE(D)	1	30.0	$\frac{6.0+5.1}{2}$	x 0.04	= 6.66m	
	1	22.0	$\frac{5.1+6.4}{2}$	x 0.04	= 5.06m	
	1	30.0	$\frac{7.6+7.1}{2}$	x 0.04	= 8.82m	
	1	30.0	$\frac{7.1+7.8}{2}$	x 0.04	= 8.94m	
	28	5 x 30.0	$\frac{7.8+7.3}{2}$	x 0.04	= 9.06m	
	1	30.0	$\frac{7.3+6.9}{2}$	x 0.04	= 8.52m	
	1	30.0	$\frac{6.9+6.9}{2}$	x 0.04	= 8.28m	
	1	28.0	$\frac{6.9+6.9}{2}$	x 0.04	= 7.72m	

MEASUREMENT BOOK

Date 1	Full description, etc, of work 2	Dimensions				Contents 7	Reference to last Measurement 8
		Number 3	Length 4	Breadth 5	Depth 6		
	1st cross (0 to 94.0 M)	1	30.0	$\frac{7.7+7.8}{2}$	$\times 0.04$	9.12 m	
		1	23.0	$\frac{7.5+7.7}{2}$	$\times 0.04$	5.45 m	
		1	41.0	$\frac{8.0+8.5}{2}$	$\times 0.04$	13.53 m	
		1	30.0	$\frac{6.9+6.9}{2}$	$\times 0.04$	8.28 m	
	3rd Main Road	1	30.0	$\frac{6.9+6.9}{2}$	$\times 0.04$	8.28 m	
	(0 to 210.0 M)	1	30.0	$\frac{6.9+6.9}{2}$	$\times 0.04$	8.28 m	
		1	30.0	$\frac{6.9+6.9}{2}$	$\times 0.04$	8.28 m	
		1	30.0	$\frac{6.9+6.9}{2}$	$\times 0.04$	8.28 m	
		1	30.0	$\frac{6.9+6.9}{2}$	$\times 0.04$	8.28 m	
		1	30.0	$\frac{6.9+7.3}{2}$	$\times 0.04$	8.52 m	
		1	30.0	$\frac{7.3+7.8}{2}$	$\times 0.04$	9.06 m	
	6 slr EE(D) 285					232.24 m	

MEASUREMENT BOOK

Date 1	Full description, etc, of work 2	Dimensions				Contents 7	Reference to last Measurement 8	Serial No. of V ne of C e of co
		Number 3	Length 4	Breadth 5	Depth 6			
I-11	Disposal of debris to the final place of disposal with all lead & lift & direction by the engineer incharge of work. vide item no ①					609.04 cum @ 72=71 Rs. - <u>44283=00</u>		
	Total Amount	4188983	=00					
	15% R/D	460711	=00					
	OR 1%	41882	=00					
		4690876	=00					
	Certificate ① certified that contractor has done the work Satisfactory. ② certified that there is no due work from contractor side ③ certified that contractor has removed all debris from work spot.							

ಸಹಾಯಕ ನಿರ್ದೇಶಕರು, ಮಂಡ್ಯ ಜಿಲ್ಲಾ ಮಾರ್ಗದರ್ಶಿ ಕಛೇರಿ, ಮಂಡ್ಯ ಜಿಲ್ಲಾ ಮಾರ್ಗದರ್ಶಿ ಕಛೇರಿ, ಮಂಡ್ಯ ಜಿಲ್ಲಾ ಮಾರ್ಗದರ್ಶಿ ಕಛೇರಿ



M. A. R. 57 (Rule 116)
Measurement Book

No. B

341717

Reference to last measurement No.
Name of Work From To
8 Name of Contractor of nature of Agency
Date of commencement of work

No.	Full description, etc., of work	Dimensions				Contents	Reference to last Measurement
		Number 3	Length 4	Breadth 5	Depth 6		
1	SM Road, Mallyandra Road		210.0M				
	3rd cross Road						
	223.0M.						
	2nd cross Road						
	Defence colony.						
	1st cross		94.0M		92.0M		
	2nd cross						
	1st cross Road						
	178.0M						
	3rd cross						
	44.0M						
	ಸಹಾಯಕ ಕಾರ್ಯವಾಹನ ಅಭಯಂಶ						
	ಶಿಕ್ಷಕರು ಉಪವಿಭಾಗ, ದಾಸರವಳ್ಳಿ ವಲ						
	ಬಿ.ಕೆ. ಬಂಗಲಾರು ಮಹಾನಗರ ಪಾ						
	ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು						

4283=00

Side
work spot.
20/5/15

Signature

